



1. Surface must be clean , dry and in sound condition prior to application.
2. Detailing of tight lap seams. Seal any voids prior to detailing.
3. Refer to the Kool Seal Specification for appropriate sealant or coating.