



1. Surface must be clean , dry and in sound condition prior to application.
2. Seal target patch with lap sealant prior to application of Kool Seal Sealant,
3. Refer to the Kool Seal Specification for appropriate sealant or coating.